
STATE OF UTAH DEPARTMENT OF NATURAL RESOURCES

DIVISION OF OIL, GAS AND MINING 1594 West North Temple Suite 1210

Box 145801

Salt Lake City, Utah 84114-5801 Telephone: (801) 538-5291

Fax: (801) 359-3940



ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

1.	Report Time Period: From (mo./yr.) 1/97 To (mo./yr.) 12/97
2.	DOGM File Number (Mine No): 5 / 003/ 032
3.	Mine Name: ENTERPRISE MILLSITE
4.	Mineral(s) Mined (or permitted to mine): PROCESSING, PACKAGING, STONE MATERIAL
5.	Type of mine
6.	Legal Description (Location of Lands Affected):
	NW 1/4, NW 1/4, NE 1/4, Section 31, Township 13 N, Range 13 W
	1/4,1/4,1/4, Section, Township, Range
	1/4,1/4,1/4, Section, Township, Range
Name	of Operator or Company: WILLIAM L BOWN
8.	Permanent Street Address: 842 WEST 400 NORTH
	City, State, Zip: WEST BOUNTIFUL, UTAH 84087
	Phone: 801-295-0601
9.	Company Representative (or designated operator):
	Name: WILLIAM L BOWN
	Title: OWNER
	Business Address: 8H2 WEST 400 NORTH
	City, State, Zip: WEST BOUNTEUL, UTAH 94087
	Phone: 801-295-0601
	\square Please check if any of the above information has changed since previous year.
<u>Minin</u>	g and Reclamation MILLSITE
1.	Was the mine active during the past year? Yes ⋈ No □
2.	If active, how much ore or mineral was mined?
3.	If inactive, what year was the mine last active?
	2. 3. 4. 5. 6. Name 8. 9.

	3.	How much additional acreage was disturbed during the past year?
	4.	Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, and volume of material moved.
	,	THERE WAS NO NEW DISTURBANCE, HOWEVER, WE DID BEGIN
		A PROCESS OF REMOVING "BULK" MATERIAL FROM AREA QUARRIES
		AND TRANSPORTING IT TO THIS MILLSITE FOR PROCESSING, PACKAGING,
		AND STORAGE. WE FIND THIS TO BE A MORE EFFICENT PROGRAM.
5		How much acreage was reclaimed during the past year?
6		Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.
		
7		What is the total disturbed acreage at years end? <u>APPROXIMATELY</u> 4.0 ACRES
8.		Briefly summarize any mining and/or reclamation plans for the upcoming year.
		PLANS ARE TO UTILIZE THE AREA IN A SIMILAR WAY
		AS LAST YEAR, BULKING MATERIAL FROM SURROUNDING QUARRIES
		INTO THE MILLSITE FOR PROCESSING, WASTE MATERIALS WILL
		BE "BACKHAULED" TO THE GUARRY AND STORED THERE FOR USE IN BACKFILLING TRENCHS AND OTHER "HOLES" CAUSED BY EXCAVATION.
NOTE:		Section III., "Additional Information" applies only to large mining operations.
NOIE.		section in., Additional information applies only to large mining operations.
III. <u>Additi</u>	onal l	Information Control of the Control o
1.		An updated surface facilities map should be attached if there have been significant changes since the previous was submitted.
2.		Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.
IV. <u>Signa</u>	ature	Requirement
I	hereb	by certify that the foregoing is true and correct.
		Name (Typed or Print): WILLIAM L BOWN
		Title of Operator: ONNER
		Signature of Operator: Dilliam L Bour
		Date: 1-29-98

jb MR-AR